### **ENVIRONMENTAL CHEMISTS**

# Analysis For Total Metals By EPA Method 200.8

Client ID: M03303
Date Received: 11/19/08
Date Extracted: 11/19/08
Date Analyzed: 11/19/08
Matrix: Water
Units: ug/L (ppb)

Client: Alaskan Copper Works
Project: PO M03303, F&BI 811213
Lab ID: 811213-01 x10
Data File: 811213-01 x10.046

Instrument: ICPMS1 Operator: hr

Lower Upper Internal Standard: % Recovery: Limit: Limit: Germanium 101 60 125

Concentration ug/L (ppb)

Chromium 462

Nickel 564

Copper 389

Zinc 43.9

### **ENVIRONMENTAL CHEMISTS**

# Analysis For Total Metals By EPA Method 200.8

Client ID: Method Blank
Date Received: Not Applicable
Date Extracted: 11/19/08
Date Analyzed: 11/19/08
Matrix: Water
Units: ug/L (ppb)

Client: Alaskan Copper Works
Project: PO M03303, F&BI 811213
Lab ID: I8-440 mb
Data File: I8-440 mb.035
Instrument: ICPMS1
Operator: hr

Upper

Limit:

125

Internal Standard: % Recovery: Limit: Germanium 112 60

Concentration ug/L (ppb)

Chromium <1
Nickel <1
Copper <1
Zinc <1

### **ENVIRONMENTAL CHEMISTS**

Date of Report: 11/21/08 Date Received: 11/19/08

Project: Metro KC Comp, PO M03303, F&BI 811213

## QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 811185-01 (Duplicate)

Analyte Chromium		Sample	Duplicate	Relative Percent	Acceptance
	Reporting Units	Result	Result	Difference	Criteria
	ug/L (ppb)	<1	<1	nm	0-20
Nickel	ug/L (ppb)	9.94	10.3	4	0-20
Copper	ug/L (ppb)	1.04	1.15	10	0-20
Zinc	ug/L (ppb)	5.69	6.26	10	0-20

Laboratory Code: 811185-01 (Matrix Spike)

				Percent	
Analyte	Reporting Units	Spike Level	Sample Result	Recovery MS	Acceptance Criteria
Analyte	Reporting Office	Level	nesun	MB	Criteria
Chromium	ug/L (ppb)	20	<1	100	50-150
Nickel	ug/L (ppb)	20	9.94	99 b	50-150
Copper	ug/L (ppb)	20	1.04	96	50-150
Zinc	ug/L (ppb)	50	5.69	93	50-150

Laboratory Code: Laboratory Control Sample

Analyte	Reporting Units	Spike Level	Percent Recovery LCS	Acceptance Criteria				
Chromium	ug/L (ppb)	20	98	70-130				
Nickel	ug/L (ppb)	20	98	70-130				
Copper	ug/L (ppb)	20	95	70-130				
Zinc	ug/L (ppb)	50	87	70-130				

#### **ENVIRONMENTAL CHEMISTS**

## **Data Qualifiers & Definitions**

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probablility.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb The analyte indicated was found in the method blank. The result should be considered an estimate.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht The sample was extracted outside of holding time. Results should be considered estimates.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- il The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr-The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve The value reported exceeded the calibration range established for the analyte. The reported concentration should be considered an estimate.
- vo The value reported fell outside the control limits established for this analyte.
- x The pattern of peaks present is not indicative of diesel.
- y The pattern of peaks present is not indicative of motor oil.

811213	~ -11-	~~~~ 1		SAMPLERS	signature)			-		·		,			se#_	A BOOT 18	ef
Send Report To Deague Trompson  Company ALASKAN Cappen whiles  Address 628 S. Hondy ST				PROJECT NAMENO.  PO#  METRO KC Comp m 03803					TURNAROUND TIME  Standard (2 Weeks)  RUSH ZYMS  Rush charges authorized by:								
ity, State, ZIP_SEA hone #2%-571-6	THE C	A 58	134	remarks Asaf	) ZYh	rs								Dispo Retur	ose af rn sai	ter 30 o mples	POSAL lays cructions
										ANA	LYS	ES REQ	UESTI	ED			
Sample ID	Lab ID	Date	Time	Sample Type	# of containers	TPH-Diesel	TPH-Gasoline	BTEX by 8021B	VOCs by 8260	SVOCs by 8270	HFS	Og Cu, 152-					Notes
m 03303	01_	11/19	12:02	420			-	+	4		1					92	A A
	32																
							-				-			-		3 103	
iedman & Bruya, Inc. 12 16th Avenue West	Relinguished by			Be	PRINT NAME CON GIERRED Thompson AC					COMP				12:42			
ottle, WA 98119-2029 . (206) 285-8282				5	S. Oborn Fd.B.					-15,3	Inc 11/19/08/12:45				12:45		

#### **ENVIRONMENTAL CHEMISTS**

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

November 21, 2008

Gerry Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on November 19, 2008 from the Metro KC Comp, PO M03303, F&BI 811213 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you should have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures ACU1121R.DOC